

INSPECTION SHEET 検品書

TRACTORS ブルドーザーなど

MAKE	CAT			MODEL	D9N		
SERIAL	1JD 01180			STAMP	1JD 01180		
HR METER	1073	HR	YEAR	1988	YR	SHOE	600G
BLADE	<input checked="" type="radio"/> S/TILT / PAT / ANGLE / OTHER			CAB/CNP	<input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / None		

ENGINE : MODEL		S/N	
Oil leakage	<input checked="" type="radio"/> OK · Attn		
Blow-By	<input checked="" type="radio"/> OK · Attn		
Sound	<input checked="" type="radio"/> OK · Attn		
Oil	<input checked="" type="radio"/> OK · Attn		
Exhaust Color	<input checked="" type="radio"/> OK · Attn		
US EPA	YES <input type="radio"/> NO <input checked="" type="radio"/>		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> OK · Attn		
Oil leakage	<input checked="" type="radio"/> OK · Attn		
Power	<input checked="" type="radio"/> OK · Attn		
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> OK · Attn		
Oil Cooler	<input checked="" type="radio"/> OK · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · NO
Transmission	<input checked="" type="radio"/> OK · Attn		
Travel	<input checked="" type="radio"/> OK · Attn		
INTERIOR			
Operator's Seat	OK <input checked="" type="radio"/> Attn	破れあり CUTS	
Inside Cover	OK <input checked="" type="radio"/> Attn	天井破れあり CEILING COVER : CUT	
Glasses	<input checked="" type="radio"/> OK · Attn		
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	<input checked="" type="radio"/> OK · Attn		
CYLD.(R)	OK · Attn		
CYLD.(L)	OK · Attn		
TILT CYLD	OK · Attn		
ANGLE CYLD	OK · Attn		

UNDERCARRIAGE See Photos. 写真参照			
COMMENT			
右側減速機付近よりオイル漏れあり			
AROUND RIGHT REDUCTION GEAR : OIL LEAKING			
Ripper	<input checked="" type="radio"/> MULTI · S/S	Shanks	2 PCS
Ripper CYLD.	<input checked="" type="radio"/> OK · Attn		
EQUALIZER BAR	OK · Attn		
BATTERY	<input checked="" type="radio"/> OK · NG		