

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2021/3/9	MAKE	CAT	MODEL	313BSR
SERIAL	CAT0313BL9PR01410		STAMP	CAT0313BL9PR01410	
HR METER	4114	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE		500G W/PADS	

ENGINE : MODEL		S/N
Oil leakage	<u>OK</u> · Attn	
Blow-By	<u>OK</u> · Attn	
Sound	<u>OK</u> · Attn	
Oil	<u>OK</u> · Attn	
Exhaust Color	<u>OK</u> · Attn	
US EPA	<u>YES</u> · NO	
MAIN PUMP		
Sound	<u>OK</u> · Attn	
Oil leakage	<u>OK</u> · Attn	
Power	<u>OK</u> · Attn	
COOLING SYSTEM		
Radiator	<u>OK</u> · Attn	
Oil Cooler	<u>OK</u> · Attn	
OPERATING SYSTEM		
Swing	<u>OK</u> · Attn	
Travel	<u>OK</u> · Attn	
INTERIOR		
Operator's Seat	<u>OK</u> · Attn	
Inside Cover	<u>OK</u> · Attn	
Glasses	<u>OK</u> · Attn	
AirCon	<u>A/C</u> · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<u>OK</u> · Attn	
Boom Cylinder	<u>OK</u> · Attn	
Arm	<u>OK</u> · Attn	
Arm Cylinder	<u>OK</u> · Attn	
BKT	<u>OK</u> · Attn	ガタあり LOOSE
BKT Cylinder	<u>OK</u> · Attn	

UNDERCARRIAGE :	See Photos. 写真参照
COMMENT	シューパッド剥がれ多数あり RUBBER PADS: ALMOST GONE
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	OK · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	ボディへコミあり FRONT COVER: DEFORMED

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。