

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2021/4/6	MAKE	KUBOTA	MODEL	U-30-3
SERIAL	NO PLATE		STAMP	30066	
HR METER	2350	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300R	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> OK · Attn	
Blow-By	<input checked="" type="radio"/> OK · Attn	
Sound	<input checked="" type="radio"/> OK · Attn	
Oil	<input checked="" type="radio"/> OK · Attn	
Exhaust Color	<input checked="" type="radio"/> OK · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> OK · Attn	
Oil leakage	<input checked="" type="radio"/> OK · Attn	
Power	<input checked="" type="radio"/> OK · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> OK · Attn	
Oil Cooler	<input checked="" type="radio"/> OK · Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> OK · Attn	
Travel	<input checked="" type="radio"/> OK · Attn	*1
INTERIOR		
Operator's Seat	<input checked="" type="radio"/> OK · Attn	
Inside Cover	OK · Attn	
Glasses	OK · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> OK · Attn	
Boom Cylinder	<input checked="" type="radio"/> OK · Attn	
Arm	<input checked="" type="radio"/> OK · Attn	
Arm Cylinder	<input checked="" type="radio"/> OK · Attn	
BKT	<input checked="" type="radio"/> OK · Attn	
BKT Cylinder	<input checked="" type="radio"/> OK · Attn	

UNDERCARRIAGE :	See Photos. 写真参照
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	OK · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
*1 増速ペダル不良 TRAVEL SPEED INCREASE PEDAL: MALFUNCTION	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。