INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2023/7/26	CATEGORY	(ON-ROAD DUMP) ・ OFF-ROAD DUMP
MAKE	ISUZU	MODEL	NJS85
SERIAL	NJS85-7005778	STAMP	NJS85-7005778
HR METER	UNKNOWN HR	ODOMETER	54387 km
TIRE SIZE	205/70R16	YEAR	YR

ENGINE : MODEL 4JJ1 S/N		
Oil leakage	(FAIR) ・ Attn	
Blow-By	FAIR ・ (Attn)	A LITTLE ・ MIDDLE ・ SEVERE *1
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・ (NO)	
OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	
COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT ・ (MT)	No. OF GEARS 5 GEARS
Transmission	(FAIR) ・ Attn	
4WD	(4WD) ・ 2WD	
Travel	(FAIR) ・ Attn	
Articulate	FAIR ・ Attn	
FOOT BRAKE	(FAIR) ・ Attn	
PARKING BRAKE	(FAIR) ・ Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR) ・ Attn	
Inside Cover	(FAIR) ・ Attn	
Glasses	FAIR ・ (Attn)	Fクラックあり WINDSHIELD: A LITTLE CRACKED
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	サビあり RUSTY
VESSEL		
MAKE	SHIN MAYWA	
VESSEL	(FAIR) ・ Attn	*2
REAR GATE TYPE	(NORMAL) ・ L-GATE (FLAT)	
REAR GATE	(FAIR) ・ Attn	*2
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

COMMENT

左右コボレーンシート破れ、補修テープあり

AUTO SHEETS: CUTS, COVERED WITH ADHESIVE TAPES

スペアタイヤ1本あり W/SPARE TIRE

*1 ブローバイ:オイルゲージ吹出し口から小

*1 A LITTLE BLOW-BY FROM OIL GAUGE OUTLET

*2 リペイント、サビあり REPAINTED, RUSTY

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。