

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2023/9/29	MAKE	KOMATSU	MODEL	D31PX-22
SERIAL	61046		STAMP	KMT0D111C01061046	
HR METER	2267	HR	SHOE	600LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL 4D95LE-5 **S/N** 530469

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS	DD	DIFF. STEERING	YES	NO
Transmission	FAIR	Attn			
Travel	FAIR	Attn			

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BLADE & CYLINDERS

BLADE	FAIR	Attn	
CYLD.(R)	FAIR	Attn	
CYLD.(L)	FAIR	Attn	
TILT CYLD	FAIR	Attn	
ANGLE CYLD	FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

COMMENT

--	--	--	--	--	--

Ripper MULTI · S/S Shanks PCS

Ripper CYLD. FAIR · Attn

EQUALIZER BAR FAIR · Attn

COMMENT

--	--	--	--	--	--

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。