

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/3/6	MAKE	KOMATSU	MODEL	PC200-11
SERIAL	504759		STAMP	KMTPC257ELC504759	
HR METER	21424	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6D107E-3 S/N 26729475

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	
Travel	FAIR	Attn	

**INTERIOR** See Photos. 写真参照

Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

**BOOM / ARM / BKT**

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

**COMMENT**

.....

.....

.....

.....

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( ) FORK GRAB ( )
Lever	LONG · WRIST ( )
Multi	MULTI · 2 · NO ( )
ARM-CRANE	YES · NO ( )
BLADE	YES · NO ( )
OFFSET	YES · NO ( )
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi ( )

**COMMENT**

MT-200 15763付属

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。