

**INSPECTION SHEET 検品書  
EXCAVATOR バックホー**

INSPECTION DATE	2024/3/6	MAKE	KOMATSU	MODEL	PC30UU-5
SERIAL	15548		STAMP	KMTPC219E04015548	
HR METER	4331	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

<b>ENGINE : MODEL</b>		<b>S/N</b>	<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		<b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	<b>4</b>
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	<b>COMMENT</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn			
Oil	<input checked="" type="radio"/> FAIR · Attn			
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			
US EPA	<input checked="" type="radio"/> YES · NO			
<b>MAIN PUMP</b>			BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )
Sound	<input checked="" type="radio"/> FAIR · Attn		Lever	LONG · <input checked="" type="radio"/> WRIST
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Multi	MULTI · 2 · <input checked="" type="radio"/> NO
Power	<input checked="" type="radio"/> FAIR · Attn		ARM-CRANE	<input checked="" type="radio"/> YES · NO 電源入らない UNABLE TO TURN ON
<b>COOLING SYSTEM</b>			BLADE	<input checked="" type="radio"/> YES · NO
Radiator	<input checked="" type="radio"/> FAIR · Attn		OFFSET	<input checked="" type="radio"/> YES · NO
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		OFFSET Cylinder	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>			Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
Swing	<input checked="" type="radio"/> FAIR · Attn		<b>COMMENT</b>	
Travel	<input checked="" type="radio"/> FAIR · Attn		警告灯点灯あり WARNING LAMP: ON	
<b>INTERIOR See Photos. 写真参照</b>				
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUTS		
Inside Cover	<input checked="" type="radio"/> FAIR · Attn			
Glasses	<input checked="" type="radio"/> FAIR · Attn			
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None			
<b>BOOM / ARM / BKT</b>				
Boom	<input checked="" type="radio"/> FAIR · Attn			
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn			
Arm	<input checked="" type="radio"/> FAIR · Attn	ガタあり LOOSE		
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn			
BKT	<input checked="" type="radio"/> FAIR · Attn			
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn			
			<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	<b>4</b>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。