

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/8	MAKE	KOMATSU	MODEL	PC120-6E
SERIAL	57345		STAMP	PC120-57345	
HR METER	8167	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	左にじみあり LEFT CYLINDER: OIL OOZING
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	<input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
両側トラックローラー不良多数あり MANY TRACK ROLLERS: MALFUNCTION	
BKT	STD <input checked="" type="radio"/> SLOPE NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi
COMMENT	
ボディヘコミ多数あり BODY: DENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。