

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/3/11	MAKE	KOBELCO	MODEL	SK200-9
SERIAL	YN13-70907		STAMP	YN13-70907	
HR METER	4066	HR	YEAR	YR	
CAB/CNP	<input checked="" type="checkbox"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>	<b>S/N</b>	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Blow-By	<input checked="" type="checkbox"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil	<input checked="" type="checkbox"/> FAIR · Attn	
Exhaust Color	<input checked="" type="checkbox"/> FAIR · Attn	
US EPA	<input checked="" type="checkbox"/> YES · NO	
<b>MAIN PUMP</b>		
Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Power	<input checked="" type="checkbox"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="checkbox"/> FAIR · Attn	
Oil Cooler	<input checked="" type="checkbox"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<input checked="" type="checkbox"/> FAIR · Attn	
Travel	<input checked="" type="checkbox"/> FAIR · Attn	
<b>INTERIOR</b>	<b>See Photos. 写真参照</b>	
Operator's Seat	<input checked="" type="checkbox"/> FAIR · Attn	破れあり CUTS
Inside Cover	<input checked="" type="checkbox"/> FAIR · Attn	
Glasses	<input checked="" type="checkbox"/> FAIR · Attn	
AirCon	<input checked="" type="checkbox"/> A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<input checked="" type="checkbox"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
Arm	<input checked="" type="checkbox"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
BKT	<input checked="" type="checkbox"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
<b>RUST</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT <input checked="" type="checkbox"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · <input checked="" type="checkbox"/> WRIST
Multi	<input checked="" type="checkbox"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="checkbox"/> YES · NO *1
BLADE	YES · <input checked="" type="checkbox"/> NO
OFFSET	YES · <input checked="" type="checkbox"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="checkbox"/> NO Breaker only · Multi
<b>COMMENT</b>	
*1 入るが警報消えない	
*1 WARNING DISPLAY (CRANE MODE: ABLE TO TURN ON)	
<b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。