

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/3/7	MAKE	CAT	MODEL	D7E
SERIAL	CAT00D7EATAN01323			STAMP	CAT00D7EATAN01323
HR METER	2697	HR	SHOE	610G	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>ENGINE : MODEL</td> <td>C9.3</td> <td>S/N</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Blow-By</td> <td>(FAIR) · Attn</td> <td colspan="2">A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Oil</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>US EPA</td> <td>(YES) · NO</td> <td></td> <td></td> </tr> <tr> <td colspan="4">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Power</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td colspan="4">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td colspan="4">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>(PS) · DD</td> <td>DIFF. STEERING</td> <td>(YES) · NO</td> </tr> <tr> <td>Transmission</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Travel</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td colspan="4">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>Operator's Seat</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Inside Cover</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>Glasses</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>AirCon</td> <td>(A/C) · H/C · H only · C only · None</td> <td></td> <td></td> </tr> <tr> <td colspan="4">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>CYLD.(R)</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>CYLD.(L)</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>TILT CYLD</td> <td>(FAIR) · Attn</td> <td></td> <td></td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> <td></td> <td></td> </tr> </table>	ENGINE : MODEL	C9.3	S/N		Oil leakage	(FAIR) · Attn			Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		Sound	(FAIR) · Attn			Oil	(FAIR) · Attn			Exhaust Color	(FAIR) · Attn			US EPA	(YES) · NO			OPERATION PUMP				Sound	(FAIR) · Attn			Oil leakage	(FAIR) · Attn			Power	(FAIR) · Attn			COOLING SYSTEM				Radiator	(FAIR) · Attn			Oil Cooler	(FAIR) · Attn			TRANSMISSION & TRAVEL				T/M TYPE	(PS) · DD	DIFF. STEERING	(YES) · NO	Transmission	(FAIR) · Attn			Travel	(FAIR) · Attn			INTERIOR See Photos. 写真参照				Operator's Seat	(FAIR) · Attn			Inside Cover	(FAIR) · Attn			Glasses	(FAIR) · Attn			AirCon	(A/C) · H/C · H only · C only · None			BLADE & CYLINDERS				BLADE	(FAIR) · Attn			CYLD.(R)	(FAIR) · Attn			CYLD.(L)	(FAIR) · Attn			TILT CYLD	(FAIR) · Attn			ANGLE CYLD	FAIR · Attn			<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>UNDERCARRIAGE See Photos. 写真参照</td> <td></td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> </td> </tr> <tr> <td>Ripper</td> <td>(MULTI) · S/S Shanks 2 PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	COMMENT		<div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div>		Ripper	(MULTI) · S/S Shanks 2 PCS	Ripper CYLD.	(FAIR) · Attn	EQUALIZER BAR	FAIR · Attn	COMMENT		<div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div>		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
ENGINE : MODEL	C9.3	S/N																																																																																																																																							
Oil leakage	(FAIR) · Attn																																																																																																																																								
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																																							
Sound	(FAIR) · Attn																																																																																																																																								
Oil	(FAIR) · Attn																																																																																																																																								
Exhaust Color	(FAIR) · Attn																																																																																																																																								
US EPA	(YES) · NO																																																																																																																																								
OPERATION PUMP																																																																																																																																									
Sound	(FAIR) · Attn																																																																																																																																								
Oil leakage	(FAIR) · Attn																																																																																																																																								
Power	(FAIR) · Attn																																																																																																																																								
COOLING SYSTEM																																																																																																																																									
Radiator	(FAIR) · Attn																																																																																																																																								
Oil Cooler	(FAIR) · Attn																																																																																																																																								
TRANSMISSION & TRAVEL																																																																																																																																									
T/M TYPE	(PS) · DD	DIFF. STEERING	(YES) · NO																																																																																																																																						
Transmission	(FAIR) · Attn																																																																																																																																								
Travel	(FAIR) · Attn																																																																																																																																								
INTERIOR See Photos. 写真参照																																																																																																																																									
Operator's Seat	(FAIR) · Attn																																																																																																																																								
Inside Cover	(FAIR) · Attn																																																																																																																																								
Glasses	(FAIR) · Attn																																																																																																																																								
AirCon	(A/C) · H/C · H only · C only · None																																																																																																																																								
BLADE & CYLINDERS																																																																																																																																									
BLADE	(FAIR) · Attn																																																																																																																																								
CYLD.(R)	(FAIR) · Attn																																																																																																																																								
CYLD.(L)	(FAIR) · Attn																																																																																																																																								
TILT CYLD	(FAIR) · Attn																																																																																																																																								
ANGLE CYLD	FAIR · Attn																																																																																																																																								
UNDERCARRIAGE See Photos. 写真参照																																																																																																																																									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																																																																								
COMMENT																																																																																																																																									
<div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div>																																																																																																																																									
Ripper	(MULTI) · S/S Shanks 2 PCS																																																																																																																																								
Ripper CYLD.	(FAIR) · Attn																																																																																																																																								
EQUALIZER BAR	FAIR · Attn																																																																																																																																								
COMMENT																																																																																																																																									
<div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 20px; margin-bottom: 5px;"></div>																																																																																																																																									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																																																																								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。