

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/8	MAKE	CAT	MODEL	320ERR
SERIAL	NO PLATE		STAMP	CAT0320ECLHN00126	
HR METER	9875 / 9891	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL S/N C8N00330

Oil leakage	FAIR	· Attn	
Blow-By	FAIR	· Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	· Attn	
Oil	FAIR	· Attn	
Exhaust Color	FAIR	· Attn	
US EPA	YES	· NO	

MAIN PUMP

Sound	FAIR	· Attn	
Oil leakage	FAIR	· Attn	
Power	FAIR	· Attn	

COOLING SYSTEM

Radiator	FAIR	· Attn	
Oil Cooler	FAIR	· Attn	

OPERATING SYSTEM

Swing	FAIR	· Attn	
Travel	FAIR	· Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	· Attn	
Inside Cover	FAIR	· Attn	
Glasses	FAIR	· Attn	
AirCon	A/C	· H/C	· H only
		· C only	· None

BOOM / ARM / BKT

Boom	FAIR	· Attn	
Boom Cylinder	FAIR	· Attn	
Arm	FAIR	· Attn	
Arm Cylinder	FAIR	· Attn	
BKT	FAIR	· <u>Attn</u>	穴あり HOLE
BKT Cylinder	FAIR	· Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

E/G関連異常表示あり WARNING DISPLAY FOR ENGINE

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。