INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/3/8	MAKE	KOMATSU	MODEL	WA200-6
SERIAL	70879			STAMP	WA105-70879
HR METER	13653 HR	Odometer	39630 km	YEAR	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25

ENGINE : MODEL 4D107E-1 S/N 26575341		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR) · Attn	破れあり CUTS
Inside Cover	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	(FAIR) · Attn	
Bell crank	FAIR · (Attn)	補修あり REPAIRED
Bucket	(FAIR) · Attn	
Articulate	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		
COMMENT			
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	(YES) · NO		
ATTACHMENTS			
STD BKT	(YES) · OTHER		
BLADE	YES · (NO)	Piping for Tilt	YES · (NO)
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。