

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/3/11	MAKE	KOMATSU	MODEL	FD120-8
SERIAL	7261		STAMP	M246-7261	
HR METER	31236	HR	Odometer	1889	km YEAR YR
CAB/CNP	<input checked="" type="radio"/> CAB	<input type="radio"/> CNP	<input type="radio"/> NONE	TIRE SIZE	10.00R20
MAX LIFTING HEIGHT	3.0	m	<input checked="" type="radio"/> VIEW	<input type="radio"/> MONO	FORK LENGTH 2360 mm
FORK SPEC	サイドシフト付 W/SIDE-SHIFT				

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	不良 MALFUNCTION
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
HYDRAULICS		
MAST Cylinder	<input checked="" type="radio"/> FAIR · Attn	
TILT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。