

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/3/11	MAKE	CAT	MODEL	D3GLGP
SERIAL	CAT00D3GVCXT00671			STAMP	CAT00D3GVCXT00671
HR METER	2861	HR	SHOE	630LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL 3046		S/N MHK17444	
Oil leakage	<input type="radio"/> FAIR · Attn		
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input type="radio"/> FAIR · Attn		
Oil	<input type="radio"/> FAIR · Attn		
Exhaust Color	<input type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input type="radio"/> FAIR · Attn		
Oil leakage	<input type="radio"/> FAIR · Attn		
Power	<input type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input type="radio"/> FAIR · Attn		
Oil Cooler	<input type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	<input type="radio"/> FAIR · Attn		
Travel	<input type="radio"/> FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<input type="radio"/> FAIR · Attn		
Inside Cover	<input type="radio"/> FAIR · Attn		
Glasses	<input type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
BLADE & CYLINDERS			
BLADE	<input type="radio"/> FAIR · Attn		
CYLD.(R)	<input type="radio"/> FAIR · Attn		
CYLD.(L)	<input type="radio"/> FAIR · Attn		
TILT CYLD	<input type="radio"/> FAIR · Attn		
ANGLE CYLD	<input type="radio"/> FAIR · Attn		

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input type="radio"/> FAIR · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。