

INSPECTION SHEET 検品書  
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/3/12	MAKE	MOROOKA	MODEL	MST-3300		
SERIAL	33103			STAMP	33103		
HR METER	6036	HR	Odometer	km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	1000R	TIRE	

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	白煙あり WHITE FUMES
US EPA	YES	NO	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS	DD	No. OF GEARS	2	GEARS
Transmission	FAIR	Attn			
Travel	FAIR	Attn			
Swing	FAIR	Attn			
Articulate	FAIR	Attn			
FOOT BRAKE	FAIR	Attn			
PARKING BRAKE	FAIR	Attn			

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	破れあり CUT		
Inside Cover	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None

MAIN FRAME

MAIN FLAME	FAIR	Attn	
------------	------	------	--

VESSEL

VESSEL	FAIR	Attn	
REAR GATE TYPE	NORMAL	L-GATE (FLAT)	
REAR GATE	FAIR	Attn	

UNDERCARRIAGE: See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

CAB内足元穴あり FLOOR IN CAB: MUCH HOLES  
バッテリー液警告灯点灯あり WARNING LAMP FOR BATTERY LIQUID: ON  
走行レバー中立になりにくい  
TRAVEL LEVER: HARD TO BE NEUTRAL  
ベッセル内部材あり SOME PARTS: PUTTING ON VESSEL

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。