

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/3/13	MAKE	CAT	MODEL	D6R
SERIAL	CAT00D6RTBRZ00129			STAMP	CAT00D6RTBRZ00129
HR METER	4967	HR	SHOE	560G	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
<b>OPERATION PUMP</b>		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
<b>COOLING SYSTEM</b>		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	(PS) · DD	DIFF. STEERING (YES) · NO
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	(FAIR) · Attn	
Inside Cover	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
<b>BLADE &amp; CYLINDERS</b>		
BLADE	(FAIR) · Attn	
CYLD.(R)	(FAIR) · Attn	
CYLD.(L)	(FAIR) · Attn	
TILT CYLD	(FAIR) · (Attn)	にじみあり OIL OOZING
ANGLE CYLD	(FAIR) · Attn	

<b>UNDERCARRIAGE See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px;">             Ripper (MULTI) · S/S Shanks 2 PCS              Ripper CYLD. (FAIR) · Attn              EQUALIZER BAR (FAIR) · Attn           </div>	
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px;">             A/Cコンプレッサー 固着あり COMPRESSOR OF A/C: STUCK              A/Cベルト欠 A/C: NO BELT           </div>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。