

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/3/13	MAKE	KOMATSU	MODEL	WA470-6
SERIAL	90069	STAMP	WA098-90069		
HR METER	17583	HR	Odometer	80285	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	26.5-25

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	ポンプ周り油汚れあり AROUND PUMP: OIL STAINS
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	*1
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	<input checked="" type="radio"/> FAIR · Attn	
Bell crank	<input checked="" type="radio"/> FAIR · Attn	
Bucket	<input checked="" type="radio"/> FAIR · Attn	
Articulate	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
STEEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING	
RIDE CONTROL	<input checked="" type="radio"/> YES · NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT	
*1 ミッション周り油汚れあり AROUND TRANSMISSION: OIL STAINS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。