

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/3/13	MAKE	CAT	MODEL	D6TLGP
SERIAL	???00D6TCSG00465 SOME LETTERS: UNREADABLE			STAMP	UNREADABLE
HR METER	7754	HR	SHOE	560G	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL	S/N	UNDERCARRIAGE	See Photos. 写真参照
Oil leakage	(FAIR) · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	(FAIR) · Attn	COMMENT	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	(YES) · NO		
OPERATION PUMP		Ripper	MULTI · S/S Shanks PCS
Sound	(FAIR) · Attn	Ripper CYLD.	(FAIR) · Attn
Oil leakage	(FAIR) · Attn	EQUALIZER BAR	(FAIR) · Attn
Power	(FAIR) · Attn	COMMENT	
COOLING SYSTEM		付属品: ブレード用台座 FIXING STAND FOR BLADE AS SPARE	
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	(PS) · DD	DIFF. STEERING	(YES) · NO
Transmission	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR		See Photos. 写真参照	
Operator's Seat	(FAIR) · Attn		
Inside Cover	(FAIR) · Attn		
Glasses	(FAIR) · Attn		
AirCon	(A/C) · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	(FAIR) · Attn		
CYLD.(R)	(FAIR) · Attn		
CYLD.(L)	(FAIR) · Attn		
TILT CYLD	(FAIR) · Attn		
ANGLE CYLD	(FAIR) · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。