

INSPECTION SHEET 検品書
OTHER その他

| | | | | | |
|-----------------|---|----------|-------------|-----------|------|
| INSPECTION DATE | 2024/3/14 | CATEGORY | PILE DRIVER | | |
| MAKE | NIPPON SHARYO | | MODEL | DHP-80 | |
| SERIAL | A89101 | | STAMP | NOT FOUND | |
| HR METER | 3520 | HR | Odometer | km | YEAR |
| CAB/CNP | ROPS CAB <input checked="" type="radio"/> CAB <input type="radio"/> ROPS CNP / CNP / NONE | | SHOE | 750G FLAT | TIRE |

| ENGINE | MODEL | S/N |
|-------------|--|--|
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | Oil <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn | Exhaust Color <input checked="" type="radio"/> FAIR · Attn |
| | | EPA YES · <input checked="" type="radio"/> NO |

| | | |
|----------------------------|--|--|
| CONDITION | <input checked="" type="radio"/> FAIR · Attn | |
| 未確認 OPERATION: NOT CHECKED | | |

| | | |
|--|---|--|
| UNDERCARRIAGE : See Photos. 写真参照 | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | |
| COMMENT | | |
| LEADER: M60DA II | | |
| HEATER | | |
| @SAKURA No.2 YARD | | |
| LEADER: 24m, BACK STAY × 2, 7t HYDRAULIC HAMMER, WEIGHT × 2 | | |
| | | |
| | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。