

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/14	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	21118		STAMP	KMTPC189V01021118	
HR METER	6164	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn

COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn

OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn

INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり TORN
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · <input checked="" type="radio"/> Attn 右にじみあり RIGHT CYLINDER: OIL OOZING
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	
両側トラックローラー摩耗、不良多数あり MANY TRACK ROLLERS: WORN, MALFUNCTION	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi

COMMENT	
ボディヘコミ多数あり BODY: MUCH DENT A/Cエラー表示あり A/C ERROR DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。