INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2026/6/4	MAKE	SAKAI	MODEL	TW502S-1
SERIAL	22054		STAMP	1TW43-22054	
HR METER	2025 / 359 HR	Odometer	- km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)		TIRE SIZE	10.5/80-16	

ENGINE : MODEL D1503-T S/N 7DJ2971		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	FAIR · (Attn)	*1
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	FAIR · (Attn)	*2
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
OTHERS		
Vibratory	(FAIR) · Attn	
Watering	(FAIR) · Attn	
Articulate	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

ハンドル曲がりあり STEERING WHEEL: DISTORTED

*1 HI/LO切替えダイヤル破損のため増速不可

*1 UNABLE TO TRAVEL AT HIGH SPEED (HI/LO SWITCH KNOB: BROKEN)

*2 座面欠、バックレスト破れあり

*2 SEAT CUSHION: MISSING, BACKREST: CUTS

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。