

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE		2024/12/19		CATEGORY		HIGH LIFT ARM for 910M			
MAKE	UNKNOWN				MODEL	UNKNOWN			
SERIAL	UNKNOWN				STAMP	NOT FOUND			
HR METER	—		HR	Odometer	km		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE			TIRE		

ENGINE	MODEL			S/N		
Oil leakage	FAIR ・ Attn			Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE		Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn			EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	—	
COMMENT		
BODY SIDE: 63 φ × 715mm		
BUCKET SIDE: 63 φ × 725mm		
未使用 UNUSED		
リンク付き W/LINK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。