

**INSPECTION SHEET 検品書**  
**WHEEL LOADER タイヤショベル**

INSPECTION DATE	2024/9/26	MAKE	YANMAR	MODEL	V3-6
SERIAL	62721		STAMP	V36-62721	
HR METER	565	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	12.5/70-16	

<b>ENGINE : MODEL</b>	S/N	N7379
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	<input type="radio"/> YES · NO	
<b>OPERATION PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	<input type="radio"/> PS · DD	
Transmission	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
FOOT BRAKE	<input type="radio"/> FAIR · Attn	
PARKING BRAKE	<input type="radio"/> FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · <input type="radio"/> H only · C only · None	
<b>FRONT &amp; CYLINDERS</b>		
Arm	<input type="radio"/> FAIR · Attn	
Bell crank	<input type="radio"/> FAIR · Attn	
Bucket	<input type="radio"/> FAIR · Attn	
Articulate	<input type="radio"/> FAIR · Attn	ガタあり LOOSE

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
右Fタイヤ釘刺さりあり NAIL: STUCK THE FRONT RIGHT TIRE	
STEERING TYPE	<input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
<b>ATTACHMENTS</b>	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。