

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                          |      |         |                   |         |
|-----------------|------------------------------------------|------|---------|-------------------|---------|
| INSPECTION DATE | 2025/7/9                                 | MAKE | KOMATSU | MODEL             | PC120-8 |
| SERIAL          | 86703                                    |      | STAMP   | KMTPC202V01086703 |         |
| HR METER        | 7544                                     | HR   | YEAR    | YR                |         |
| CAB/CNP         | (ROPS CAB) / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G              |         |

|                                       |       |          |                            |                |
|---------------------------------------|-------|----------|----------------------------|----------------|
| <b>ENGINE : MODEL</b>                 |       | 4D95LE-5 | <b>S/N</b>                 | 546803         |
| Oil leakage                           | FAIR  | Attn     |                            |                |
| Blow-By                               | FAIR  | Attn     | A LITTLE · MIDDLE · SEVERE |                |
| Sound                                 | FAIR  | Attn     |                            |                |
| Oil                                   | FAIR  | Attn     |                            |                |
| Exhaust Color                         | FAIR  | Attn     |                            |                |
| US EPA                                | YES   | NO       |                            |                |
| <b>MAIN PUMP</b>                      |       |          |                            |                |
| Sound                                 | FAIR  | Attn     |                            |                |
| Oil leakage                           | FAIR  | Attn     |                            |                |
| Power                                 | FAIR  | Attn     |                            |                |
| <b>COOLING SYSTEM</b>                 |       |          |                            |                |
| Radiator                              | FAIR  | Attn     |                            |                |
| Oil Cooler                            | FAIR  | Attn     |                            |                |
| <b>OPERATING SYSTEM</b>               |       |          |                            |                |
| Swing                                 | FAIR  | Attn     |                            |                |
| Travel                                | FAIR  | Attn     |                            |                |
| <b>INTERIOR      See Photos. 写真参照</b> |       |          |                            |                |
| INTERIOR COND.                        | CLEAN | FAIR     | DIRTY                      |                |
| Operator's Seat                       | FAIR  | Attn     | 破れあり TORN                  |                |
| Glasses                               | FAIR  | Attn     |                            |                |
| AirCon                                | A/C   | H/C      | H only                     | C only    None |
| <b>BOOM / ARM / BKT</b>               |       |          |                            |                |
| Boom                                  | FAIR  | Attn     |                            |                |
| Boom Cylinder                         | FAIR  | Attn     | *1                         |                |
| Arm                                   | FAIR  | Attn     | ガタあり LOOSE                 |                |
| Arm Cylinder                          | FAIR  | Attn     |                            |                |
| BKT                                   | FAIR  | Attn     | ガタあり LOOSE                 |                |
| BKT Cylinder                          | FAIR  | Attn     | にじみあり OIL Oozing           |                |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。