

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE		2026/7/2		CATEGORY		ROTATABLE CUTTER for 0.45m3			
MAKE	UNKNOWN				MODEL	UNKNOWN			
SERIAL	NO PLATE				STAMP	NOT FOUND			
HR METER	- HR		Odometer	km			YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE			TIRE		

ENGINE	MODEL		S/N		
Oil leakage	FAIR · Attn		Oil	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR · Attn	
Sound	FAIR · Attn		EPA	YES · NO	

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR		
COMMENT 65 φ × 260mm					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					
		2			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。