

INSPECTION SHEET 検品書
OTHER その他

| | | | | | | | | | |
|-----------------|--|----------|----------|----------|-------|-------------------|------|----|--|
| INSPECTION DATE | | 2022/3/4 | | CATEGORY | | BREAKER for 0.2m3 | | | |
| MAKE | KONAN | | | | MODEL | MKB300M | | | |
| SERIAL | 1330M | | | | STAMP | NOT FOUND | | | |
| HR METER | - HR | | Odometer | km | | | YEAR | YR | |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | | SHOE | | | TIRE | | |

| ENGINE | MODEL | | S/N | | |
|-------------|-------------|----------------------------|---------------|-------------|--|
| Oil leakage | FAIR • Attn | | Oil | FAIR • Attn | |
| Blow-By | FAIR • Attn | A LITTLE • MIDDLE • SEVERE | Exhaust Color | FAIR • Attn | |
| Sound | FAIR • Attn | | EPA | YES • NO | |

| | | |
|----------------------------|-------------|--|
| CONDITION | FAIR . Attn | |
| 未確認 OPERATION: NOT CHECKED | | |
| | | |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。