

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/30	MAKE	KOBELCO	MODEL	SK75SR-3
SERIAL	YT07-28098		STAMP	YT07-28098	
HR METER	4008	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		4LE2	S/N	624481
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn	A LITTLE • MIDDLE • SEVERE	
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	YES	☒ NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn	*1	
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり TORN	
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	☐ H/C ☐ H only ☐ C only ☐ None		
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	Attn		
Arm	☒ FAIR	Attn		
Arm Cylinder	☒ FAIR	Attn		
BKT	☒ FAIR	Attn		
BKT Cylinder	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	☒ YES • NO
BLADE	☒ YES • NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	☒ YES • NO Breaker only • ☒ Multi
COMMENT	
*1 ポンプ下ホース周りにじみあり	
*1 AROUND HOSES UNDER THE PUMP: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。