INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025/4/3			MAKE		IHI		MC	DDEL	IC100-2		
SERIAL	CB001268				-	-	STAMP			CB001268			
HR METER	8102 HR			Od	ometer		ŀ	ĸm	YEAR			YR	
CAB/CNP	ROPS CA	AB CA	B RC	PS CN	NP / CNP /	/ NONE	SHOE		7501	₹	TIRE		
ENGINE: MODEL S/N							MAIN FRAME						
Oil leakage	FAIR · Attn						MAIN FL/	AME	FAIR	■ Attn			
Blow-By	FAIR · Attn	A LITTLI	E · MIDI	DLE •	SEVERE		VESSEL	•		•			
Sound	FAIR · Attn						VESSE	L	FAIR	■ Attn			
Oil	FAIR · Attn						REAR GATE	TYPE	N	ORMAL	. · L-	-GATE (FLAT)	
Exhaust Color	FAIR · Attn						REAR GA	ATE	FAIR	Attn			
US EPA	YES · NO						UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP							RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						
Sound	FAIR · Attn						TIRE WE	AR	FA	IR · W	ORN • UI	NEVEN WEAR	
Oil leakage	FAIR · Attn						COMMENT	_					
Power	FAIR · Attn						シュー摩耗	あり	RUE	BER T	RACKS: \	WORN	
COOLING	SYSTEM												
Radiator	FAIR · Attn												
Oil Cooler	FAIR · Attn												
TRANSMISSION & TRAVEL													
T/M TYPE	PS) · DD			No. 0	OF GEARS -	GEARS							
Transmission	FAIR · Attn			·	·								
Travel	FAIR · Attn												
Swing	FAIR · Attn												
Articulate	FAIR · Attn												
FOOT BRAKE	FAIR · Attn												
PARKING BRAKE	FAIR · Attn												
INTERIOR See Photos. 写真参照													
INTERIOR COND.	CLEAN	• F	AIR •		DIRTY								
Operator's Seat	FAIR · Attn												
Glasses	FAIR · Attn												
AirCon	A/C).	H/C	• H onl	у •	C only	None	RUST of BODY	(5: NONE	, 4: A L	ITTLE, 3: M	IIDDLE, 2: MU	CH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。