INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2026/6/10	CATEGORY	(GENERATOR) / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-13LSYB	
SERIAL	3900914		STAMP	NOT FOUND	
HR METER	9808 HR	TIRE SIZE		YEAR	YR

ENGINE :	**MODEL**	YANMAR 3TNV84		**S/N**		60892	
Oil leakage	(FAIR) · Attn			Oil	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		Exhaust Color	(FAIR) · Attn		
Sound	(FAIR) · Attn			Radiator	(FAIR) · Attn		

GENERATOR						
RATED POWER	10.5 / 13.0	KVA	Leaking Breaker Condition	(FAIR) · Attn		
RATED AMPERE	30.3 / 34.1	A	Insulation Condition	(FAIR) · Attn		
Output Terminal	(FAIR) · Attn					

COMPRESSOR					
RATED PRESSURE	Mpa Kgf/cm2	Unload Condition	FAIR · Attn		
RATED AIR FLOW	m3/min	Receiver Tank Condition	FAIR · Attn		
Compressor Oil Leak	FAIR · Attn	Safety Valve Condition	FAIR · Attn		

CONDITION	(FAIR) · Attn		

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENTS

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。