

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2025/8/1	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	NIPPON SHARYO		MODEL	NES60TKL	
SERIAL	KR010600		STAMP	NOT FOUND	
HR METER	9004	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	V3800-T	S/N	2EW0060	
Oil leakage	<input checked="" type="radio"/> FAIR ▪ Attn		Oil	<input checked="" type="radio"/> FAIR ▪ Attn	
Blow-By	<input checked="" type="radio"/> FAIR ▪ Attn	A LITTLE ▪ MIDDLE ▪ SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR ▪ Attn	
Sound	<input checked="" type="radio"/> FAIR ▪ Attn		Radiator	<input checked="" type="radio"/> FAIR ▪ Attn	

GENERATOR					
RATED POWER	50 / 60	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR ▪ Attn	
RATED AMPERE	144, 72.2 / 157, 78.7	A	Insulation Condition	<input checked="" type="radio"/> FAIR ▪ Attn	
Output Terminal	<input checked="" type="radio"/> FAIR ▪ Attn				

COMPRESSOR					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	FAIR ▪ Attn	
RATED AIR FLOW		m3/min	Receiver Tank Condition	FAIR ▪ Attn	
Compressor Oil Leak	FAIR ▪ Attn		Safety Valve Condition	FAIR ▪ Attn	

CONDITION	<input checked="" type="radio"/> FAIR ▪ Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR
--------------------------------------------------------------	---	-----------	---------------------------

COMMENTS <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。