

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/21	MAKE	KOBELCO	MODEL	SK70SR-2
SERIAL	YT06-18009		STAMP	YT06-18009	
HR METER	5052	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL 4LE2 S/N 238744	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn
Travel	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn ガタあり LOOSE
Boom Cylinder	FAIR • Attn 油漏れあり OIL LEAKING
Arm	FAIR • Attn
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn ガタあり LOOSE
BKT Cylinder	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。