

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/10	MAKE	KOMATSU	MODEL	D31PX-22
SERIAL	61092		STAMP	KMT0D111H01061092	
HR METER	3827	HR	SHOE	590LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL 4D95LE-5 S/N 532683	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD DIFF. STEERING YES · NO
Transmission	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり CUT
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BLADE & CYLINDERS	
BLADE	FAIR · Attn
CYLD.(R)	FAIR · Attn
CYLD.(L)	FAIR · Attn
TILT CYLD	FAIR · Attn
ANGLE CYLD	FAIR · Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Ripper MULTI · S/S Shanks PCS	
Ripper CYLD.	FAIR · Attn
COMMENT	
左レバー(ステアリング側)中立甘い、 中立が甘いためセル回す時に調整が必要 LEFT STEERING LEVER: HARD TO KEEP AT THE NEUTRAL POSITION (NEED TO SET THE LEVER AT THE NEUTRAL POSITION WHEN STARTING THE ENGINE)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。