

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2023/8/21	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	22866	STAMP	KMTPC189V01022866		
HR METER	7117	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G		

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR · <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · <input checked="" type="radio"/> Attn	
Oil	FAIR · <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR · <input checked="" type="radio"/> Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	FAIR · <input checked="" type="radio"/> Attn	
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	
Power	FAIR · <input checked="" type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR · <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR · <input checked="" type="radio"/> Attn	
OPERATING SYSTEM		
Swing	FAIR · <input checked="" type="radio"/> Attn	
Travel	FAIR · <input checked="" type="radio"/> Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり TORN
Inside Cover	FAIR · <input checked="" type="radio"/> Attn	
Glasses	FAIR · <input checked="" type="radio"/> Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · <input checked="" type="radio"/> Attn	
Boom Cylinder	FAIR · <input checked="" type="radio"/> Attn	左右シリンダー油漏れ小 CYLINDERS: OIL LEAKING
Arm	FAIR · <input checked="" type="radio"/> Attn	
Arm Cylinder	FAIR · <input checked="" type="radio"/> Attn	
BKT	FAIR · <input checked="" type="radio"/> Attn	
BKT Cylinder	FAIR · <input checked="" type="radio"/> Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
Lever	LONG · <input type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · <input checked="" type="radio"/> Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
COMMENT	
*1 オイルパン周り油漏れ小 AROUND OIL PAN: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。