

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/17	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	23299		STAMP	KMTPC189J01023299	
HR METER	6718	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G		

ENGINE : MODEL 4D95LE-5 S/N 504988	UNDERCARRIAGE : See Photos. 写真参照
Oil leakage <input type="radio"/> FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
Blow-By <input type="radio"/> FAIR · <input checked="" type="radio"/> Attn A LITTLE <input checked="" type="radio"/> MIDDLE SEVERE *1	COMMENT
Sound <input type="radio"/> FAIR · Attn	
Oil <input type="radio"/> FAIR · Attn	
Exhaust Color <input type="radio"/> FAIR · Attn	
US EPA <input checked="" type="radio"/> YES · NO	
MAIN PUMP	
Sound <input type="radio"/> FAIR · Attn	
Oil leakage <input type="radio"/> FAIR · Attn	
Power <input type="radio"/> FAIR · Attn	
COOLING SYSTEM	BKT <input type="radio"/> STD / <input checked="" type="radio"/> SLOPE / NARROW / SKELETON / OTHER()
Radiator <input type="radio"/> FAIR · Attn	Lever LONG · <input checked="" type="radio"/> WRIST
Oil Cooler <input type="radio"/> FAIR · Attn	Multi <input checked="" type="radio"/> MULTI · 2 · NO
OPERATING SYSTEM	ARM-CRANE <input checked="" type="radio"/> YES · NO
Swing <input type="radio"/> FAIR · Attn	BLADE YES · <input checked="" type="radio"/> NO
Travel <input type="radio"/> FAIR · Attn	OFFSET YES · <input checked="" type="radio"/> NO
INTERIOR See Photos. 写真参照	OFFSET Cylinder FAIR · Attn
Operator's Seat <input type="radio"/> FAIR · Attn 破れあり TORN	Piping YES · <input checked="" type="radio"/> NO Breaker only · Multi
Inside Cover <input type="radio"/> FAIR · Attn	COMMENT *1 オイル吐出しあり OIL SPURTING
Glasses <input type="radio"/> FAIR · Attn	
AirCon <input checked="" type="radio"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT	
Boom <input type="radio"/> FAIR · Attn	
Boom Cylinder <input type="radio"/> FAIR · Attn	
Arm <input type="radio"/> FAIR · Attn	
Arm Cylinder <input type="radio"/> FAIR · Attn	
BKT <input type="radio"/> FAIR · Attn	
BKT Cylinder <input type="radio"/> FAIR · Attn	
	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。