

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/18	MAKE	HITACHI	MODEL	ZX350K-6
SERIAL	HCMDDQA4P00080572		STAMP	HCMDDQA4P00080572	
HR METER	7163	HR	YEAR	2018	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL	6HK1	S/N	
Oil leakage	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Blow-By	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Oil	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Exhaust Color	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
US EPA	<input type="radio"/> YES	<input type="checkbox"/> NO	
MAIN PUMP			
Sound	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Oil leakage	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Power	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
COOLING SYSTEM			
Radiator	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Oil Cooler	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
OPERATING SYSTEM			
Swing	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Travel	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Inside Cover	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Glasses	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
AirCon	<input type="radio"/> A/C	<input type="checkbox"/> H/C	<input type="checkbox"/> H only · <input type="checkbox"/> C only · None
BOOM / ARM / BKT			
Boom	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Boom Cylinder	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
Arm Cylinder	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	
BKT	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	ガタあり LOOSE
BKT Cylinder	<input type="radio"/> FAIR	<input type="checkbox"/> Attn	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
BKT	STD / SLOPE / NARROW	<input type="radio"/> SKELETON OTHER()	
Lever	LONG · <input type="radio"/> WRIST		
Multi	<input type="radio"/> MULTI · 2 · NO		
ARM-CRANE	YES · <input type="radio"/> NO		
BLADE	YES · <input type="radio"/> NO		
OFFSET	YES · <input type="radio"/> NO		
OFFSET Cylinder	FAIR · <input type="checkbox"/> Attn		
Piping	<input type="radio"/> YES · <input type="checkbox"/> NO	Breaker only · <input type="radio"/> Multi	
COMMENT			
ONE-TOUCH			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。