

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダ

INSPECTION DATE	2024/4/16	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-100ESI	
SERIAL	3852268		STAMP	NOT FOUND	
HR METER	2740	HR	TIRE SIZE	YEAR	YR

ENGINE :		MODEL	ISUZU 6BG1T	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn		Oil	<input checked="" type="radio"/> FAIR
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR
Sound	<input checked="" type="radio"/> FAIR	Attn		Radiator	<input checked="" type="radio"/> FAIR

GENERATOR					
RATED POWER	80 / 100		KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR
RATED AMPERE	231, 115 / 262, 131		A	Insulation Condition	<input checked="" type="radio"/> FAIR
Output Terminal	<input checked="" type="radio"/> FAIR	Attn			

COMPRESSOR					
RATED PRESSURE			Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR
RATED AIR FLOW			m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR
Compressor Oil Leak	<input checked="" type="radio"/> FAIR	Attn		Safety Valve Condition	<input checked="" type="radio"/> FAIR

CONDITION	<input checked="" type="radio"/> FAIR	Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
---	---	--

COMMENTS

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。