

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/5/2	MAKE	UNI CARRIERS	MODEL	704
SERIAL	56N30349		STAMP	NOT FOUND	
HR METER	45134	HR	Odometer	-	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	4.50-12 (SOLID)

<b>ENGINE : MODEL</b>		<b>S/N</b>	
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
<b>OPERATION PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<u>PS</u> · DD		
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
FOOT BRAKE	FAIR · <u>Attn</u> *1		
PARKING BRAKE	FAIR · <u>Attn</u> *1		
<b>INTERIOR</b> See Photos. 写真参照			
Operator's Seat	FAIR · <u>Attn</u>	破れあり CUTS	
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>FRONT &amp; CYLINDERS</b>			
Arm	<u>FAIR</u> · Attn		
Bell crank	FAIR · Attn		
Bucket	FAIR · Attn		
Articulate	FAIR · Attn		

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b> タイヤ摩耗大 TIRES: MUCH WORN	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / <u>LEVER STEERING</u>
RIDE CONTROL	YES · <u>NO</u>
<b>ATTACHMENTS</b>	
STD BKT	YES · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt <u>YES</u> · NO
<b>COMMENT</b> アタッチメントなし WITHOUT ATTACHMENT *1 効かない、ペダル固着あり MALFUNCTION, PEDAL: STUCK	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。