

INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2024/4/23	CATEGORY	<input checked="" type="radio"/> GENERATOR / <input type="radio"/> COMPRESSOR / <input type="radio"/> WELDER		
MAKE	AIRMAN	MODEL	SDG13S		
SERIAL	1393A50106	STAMP	NOT FOUND		
HR METER	8760	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	3LD1	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR ▪ Attn	Oil	<input checked="" type="radio"/> FAIR ▪ Attn	
Blow-By	<input checked="" type="radio"/> FAIR ▪ Attn	A LITTLE ▪ MIDDLE ▪ SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR ▪ Attn
Sound	<input checked="" type="radio"/> FAIR ▪ Attn	Radiator	<input checked="" type="radio"/> FAIR ▪ Attn	

GENERATOR				
RATED POWER	10.5 / 13	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR ▪ Attn
RATED AMPERE		A	Insulation Condition	<input checked="" type="radio"/> FAIR ▪ Attn
Output Terminal	<input checked="" type="radio"/> FAIR ▪ Attn			

COMPRESSOR				
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR ▪ Attn
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR ▪ Attn
Compressor Oil Leak	<input checked="" type="radio"/> FAIR ▪ Attn		Safety Valve Condition	<input checked="" type="radio"/> FAIR ▪ Attn

CONDITION	<input checked="" type="radio"/> FAIR ▪ Attn
-----------	--

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENTS
燃料フィルターホースより燃料漏れ小 FUEL FILTER HOSE: FUEL LEAKING

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。