

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2024/4/25	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-45LSKB	
SERIAL	3908345		STAMP	NOT FOUND	
HR METER	15323	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	V3800-T	S/N	2GA2942	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Oil	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
Sound	<input checked="" type="radio"/> FAIR · Attn		Radiator	<input checked="" type="radio"/> FAIR · Attn	

GENERATOR					
RATED POWER	37 / 45	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR · Attn	
RATED AMPERE	107 / 118	A	Insulation Condition	<input checked="" type="radio"/> FAIR · Attn	
Output Terminal	<input checked="" type="radio"/> FAIR · Attn				

COMPRESSOR					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR · Attn	
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR · Attn	
Compressor Oil Leak	<input checked="" type="radio"/> FAIR · Attn		Safety Valve Condition	<input checked="" type="radio"/> FAIR · Attn	

CONDITION	<input checked="" type="radio"/> FAIR · Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
--	---	--

COMMENTS

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。