

**INSPECTION SHEET 検品書**  
**GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー**

INSPECTION DATE	2024/4/22	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	HOKUETSU		MODEL	SDG45S-7B1	
SERIAL	1337B11171		STAMP	NOT FOUND	
HR METER	14972	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	V3800-T	S/N	2GC0532	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Oil	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
Sound	<input checked="" type="radio"/> FAIR · Attn		Radiator	<input checked="" type="radio"/> FAIR · Attn	

<b>GENERATOR</b>					
RATED POWER	37 / 45	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR · Attn	
RATED AMPERE		A	Insulation Condition	<input checked="" type="radio"/> FAIR · Attn	
Output Terminal	<input checked="" type="radio"/> FAIR · Attn				

<b>COMPRESSOR</b>					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR · Attn	
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR · Attn	
Compressor Oil Leak	<input checked="" type="radio"/> FAIR · Attn		Safety Valve Condition	<input checked="" type="radio"/> FAIR · Attn	

CONDITION	<input checked="" type="radio"/> FAIR · Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
--	---	--

<b>COMMENTS</b>
<div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。