

**INSPECTION SHEET 検品書**  
**GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダ**

INSPECTION DATE	2024/4/25	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-60LSIB	
SERIAL	3906569		STAMP	NOT FOUND	
HR METER	17179	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	4JJ1	S/N	196908
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Oil	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
Sound	<input checked="" type="radio"/> FAIR · Attn		Radiator	<input checked="" type="radio"/> FAIR · Attn

<b>GENERATOR</b>				
RATED POWER	50 / 60	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR · Attn
RATED AMPERE	144 / 157	A	Insulation Condition	<input checked="" type="radio"/> FAIR · Attn
Output Terminal	<input checked="" type="radio"/> FAIR · Attn			

<b>COMPRESSOR</b>				
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR · Attn
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR · Attn
Compressor Oil Leak	<input checked="" type="radio"/> FAIR · Attn		Safety Valve Condition	<input checked="" type="radio"/> FAIR · Attn

CONDITION	<input checked="" type="radio"/> FAIR · Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
--	---	--

<b>COMMENTS</b>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。