

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2024/4/23	CATEGORY	GENERATOR / COMPRESSOR / WELDER	
MAKE	DENYO	MODEL	DCA-60LSIB	
SERIAL	3910683	STAMP	NOT FOUND	
HR METER	13078	HR	TIRE SIZE	YEAR YR

ENGINE :	MODEL	4JJ1	S/N	204151
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	Oil	<input checked="" type="radio"/> FAIR
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE	MIDDLE
			SEVERE	Exhaust Color
Sound	<input checked="" type="radio"/> FAIR	Attn	Radiator	<input checked="" type="radio"/> FAIR

GENERATOR				
RATED POWER	50 / 60	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR
RATED AMPERE	144 / 157	A	Insulation Condition	<input checked="" type="radio"/> FAIR
Output Terminal	<input checked="" type="radio"/> FAIR	Attn		

COMPRESSOR				
RATED PRESSURE		Mpa Kg/cm ²	Unload Condition	<input checked="" type="radio"/> FAIR
RATED AIR FLOW		m ³ /min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR
Compressor Oil Leak	<input checked="" type="radio"/> FAIR	Attn	Safety Valve Condition	<input checked="" type="radio"/> FAIR

CONDITION	<input checked="" type="radio"/> FAIR	Attn
-----------	---------------------------------------	------

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENTS

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。