

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/5/10	MAKE	KOMATSU	MODEL	PC78US-6N0
SERIAL	10513		STAMP	KMTPC030A0101513	
HR METER	7451	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450G		

ENGINE : MODEL 4D95LE-3 S/N 118509

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	破れあり CUTS
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	摩耗あり WORN
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

右走行モーター周り油漏れ小
AROUND RIGHT TRAVEL MOTOR: OIL LEAKING

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())

Lever LONG · (WRIST)

Multi (MULTI) · 2 · NO

ARM-CRANE YES · (NO)

BLADE (YES) · NO

OFFSET YES · (NO)

OFFSET Cylinder FAIR · Attn

Piping (YES) · NO Breaker only · (Multi)

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。