

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/6/3	MAKE	TCM	MODEL	711
SERIAL	56U00164		STAMP	B11-00164	
HR METER	UNKNOWN	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	12-16.5 8PR	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
FOOT BRAKE	FAIR · <input checked="" type="radio"/> Attn	効かない MALFUNCTION
PARKING BRAKE	FAIR · <input checked="" type="radio"/> Attn	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり CUTS
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
FRONT & CYLINDERS		
Arm	<input type="radio"/> FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · <input checked="" type="radio"/> Attn	自然降下あり HYDRAULIC DRIFT
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
F下周りより油漏れ小 FRONT PART OF BOTTOM: OIL LEAKING	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / <input checked="" type="radio"/> LEVER STEERING
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT	
HRメーター故障あり HR METER: MALFUNCTION	
安全レバー効かない SAFETY LEVER: MALFUNCTION	
作動油、燃料キャップカバー欠品	
HYDRAULIC OIL FILLER CAP COVER & FUEL FILLER CAP COVER: MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。