

INSPECTION SHEET 検品書  
LIFTING PLATFORM 高所作業車

INSPECTION DATE		2024/6/28		MAKE		AICHI		MODEL		RV041	
SERIAL No.	PLATE : 646382					STAMP : NOT FOUND					
HR METER	UNKNOWN		HR	Odometer		km			YEAR	YR	
CHASSIS	MODEL -					No. -					
SHOE	200R					TIRE SIZE					
MAX HIGHT	4.0 m					MAX WEIGHT		200 kg			

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT • MT	No. OF GEARS
Transmission	FAIR • Attn	
4WD	4WD • 2WD	
Travel	FAIR • Attn	
Swing	FAIR • Attn	
FOOT BRAKE	FAIR • Attn	
PARKING BRAKE	FAIR • Attn	
BOOM		
No. of Section	-	SECTIONS
DERRICKING CYL.	FAIR • Attn	
EXTENSION CYL.	FAIR • Attn	

INTERIOR		See Photos. 写真参照
Operator's Seat	FAIR • Attn	
Inside Cover	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
OUTRIGGERS		
X • H		
OUTRIGGERS COND.		FAIR • Attn
COMMENT		
電動作業車 BATTERY STYLE		
ホーン不良 HORN: MALFUNCTION		
電源、定荷重ランプ不良		
POWER LIGHT & CONSTANT LOAD LAMP: MALFUNCTION		
バッテリー充電しても弱い(走行遅い、アーム動かない)、 充電がすぐに切れる(ほぼ不動状態)		
WEAK POWER EVEN CHARGED BATTERY		
(SLOW TRAVELING, ARM: NOT WORKING),		
BATTERY : UNABLE TO LAST FOR 15 MINUTES		
(ALMOST IMMOVABLE MACHINE)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。