

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |          |
|-----------------|----------------------------------------|------|---------|-------|----------|
| INSPECTION DATE | 2024/7/4                               | MAKE | KOMATSU | MODEL | PC20MR-1 |
| SERIAL          | 11256                                  |      | STAMP   | 11256 |          |
| HR METER        | 5145                                   | HR   | YEAR    | YR    |          |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 250R  |          |

ENGINE : MODEL S/N

|               |             |                            |
|---------------|-------------|----------------------------|
| Oil leakage   | FAIR · Attn |                            |
| Blow-By       | FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound         | FAIR · Attn |                            |
| Oil           | FAIR · Attn |                            |
| Exhaust Color | FAIR · Attn |                            |
| US EPA        | YES · NO    |                            |

MAIN PUMP

|             |             |  |
|-------------|-------------|--|
| Sound       | FAIR · Attn |  |
| Oil leakage | FAIR · Attn |  |
| Power       | FAIR · Attn |  |

COOLING SYSTEM

|            |             |  |
|------------|-------------|--|
| Radiator   | FAIR · Attn |  |
| Oil Cooler | FAIR · Attn |  |

OPERATING SYSTEM

|        |             |  |
|--------|-------------|--|
| Swing  | FAIR · Attn |  |
| Travel | FAIR · Attn |  |

INTERIOR See Photos. 写真参照

|                 |                                    |                |
|-----------------|------------------------------------|----------------|
| Operator's Seat | FAIR · Attn                        | 破れあり HUGE CUTS |
| Inside Cover    | FAIR · Attn                        |                |
| Glasses         | FAIR · Attn                        |                |
| AirCon          | A/C · H/C · H only · C only · None |                |

BOOM / ARM / BKT

|               |             |                  |
|---------------|-------------|------------------|
| Boom          | FAIR · Attn | ガタあり LOOSE       |
| Boom Cylinder | FAIR · Attn | 油漏れ小 OIL LEAKING |
| Arm           | FAIR · Attn | ガタあり LOOSE       |
| Arm Cylinder  | FAIR · Attn |                  |
| BKT           | FAIR · Attn | ガタあり LOOSE       |
| BKT Cylinder  | FAIR · Attn |                  |

UNDERCARRIAGE : See Photos. 写真参照

|                                                              |   |
|--------------------------------------------------------------|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--------------------------------------------------------------|---|

COMMENT

|                 |                                             |
|-----------------|---------------------------------------------|
| BKT             | STD (SLOPE) / NARROW / SKELETON / OTHER ( ) |
| Lever           | LONG · WRIST                                |
| Multi           | MULTI · 2 · NO                              |
| ARM-CRANE       | YES · NO                                    |
| BLADE           | YES · NO                                    |
| OFFSET          | YES · NO                                    |
| OFFSET Cylinder | FAIR · Attn                                 |
| Piping          | YES · NO Breaker only · Multi               |

COMMENT

|                                                                      |   |
|----------------------------------------------------------------------|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|----------------------------------------------------------------------|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。