

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/23	MAKE	KOMATSU	MODEL	D21P-8
SERIAL	84337		STAMP	NOT FOUND	
HR METER	1624	HR	SHOE	510LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	DIFF. STEERING YES · NO
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BLADE & CYLINDERS		
BLADE	FAIR · Attn	*1
CYLD.(R)	FAIR · Attn	
CYLD.(L)	FAIR · Attn	
TILT CYLD	FAIR · Attn	
ANGLE CYLD	FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
EQUALIZER BAR	FAIR · Attn		
COMMENT			
トリミングドーザー TRIMMING DOZER			
CNP補修あり CNP: REPAIRED			
*1 補修、アームクラックあり REPAIRED, ARMS: CRACKED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。