

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/18	MAKE	CAT		MODEL	950K	
SERIAL	CAT0950KKFER00252			STAMP	CAT0950KKFER00252		
HR METER	13627	HR	Odometer	54310	km	YEAR	YR
CAB/CNP	<input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25		

ENGINE : MODEL	C7.1	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	Fひび割れあり WINDSHIELD: CRACKED
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	<input checked="" type="radio"/> FAIR · Attn	
Bell crank	<input checked="" type="radio"/> FAIR · Attn	
Bucket	<input checked="" type="radio"/> FAIR · Attn	
Articulate	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
STEERING TYPE	<input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING		
RIDE CONTROL	<input checked="" type="radio"/> YES · NO		
ATTACHMENTS			
STD BKT	<input checked="" type="radio"/> YES · OTHER		
BLADE	<input checked="" type="radio"/> YES · <input type="radio"/> NO	Piping for Tilt	<input checked="" type="radio"/> YES · <input type="radio"/> NO
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。