

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2024/10/21	MAKE	HITACHI	MODEL	ZX145W-3
SERIAL	JK6CFB00900010046			STAMP	JK6CFB00900010046
HR METER	12226	HR	Odometer	9373	km
CAB/CNP	ROPS CAB / CAB / ROPS	CNP / CNP / NONE	TIRE SIZE	10.00-20	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR	Attn
Inside Cover	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT STD / SLOPE / NARROW / SKELETON OTHER)	
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO *1
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi
OUTRIGGERS COND.	FAIR Attn
COMMENT	
アタッチメント: クラムシェルバケット ATTACHMENT: CLAMSHELL BUCKET	
*1 入るが警告灯出っ放し	
*1 WARNING DISPLAY (CRANE MODE: ABLE TO TURN ON)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。