

INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダ－

INSPECTION DATE	2024/8/7	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO	MODEL	DCA-150ESM		
SERIAL	3854424	STAMP	NOT FOUND		
HR METER	ERROR	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	MITSUBISHI 6D16-TLE2D	S/N		
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	Oil	<input checked="" type="radio"/> FAIR	Attn
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE	<input checked="" type="radio"/> FAIR	Attn
			MIDDLE		
			SEVERE		
Sound	<input checked="" type="radio"/> FAIR	Attn	Radiator	<input checked="" type="radio"/> FAIR	Attn

GENERATOR					
RATED POWER	125 / 150	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR	Attn
RATED AMPERE	361, 180 / 394, 197	A	Insulation Condition	<input checked="" type="radio"/> FAIR	Attn
Output Terminal	<input checked="" type="radio"/> FAIR	Attn			

COMPRESSOR					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input checked="" type="radio"/> FAIR	Attn
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input checked="" type="radio"/> FAIR	Attn
Compressor Oil Leak	<input checked="" type="radio"/> FAIR	Attn	Safety Valve Condition	<input checked="" type="radio"/> FAIR	Attn

CONDITION	<input checked="" type="radio"/> FAIR	Attn			

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
--	---	--

COMMENTS	<div style="border: 1px solid black; height: 250px; margin-top: 5px;"> <!-- Representing the grid of horizontal lines --> </div>
-----------------	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。